Update Content

1. Summary

Software Optimization

2. New Function

Added service mileage reset and reminders for the change of brake pads

3. Optimized Functions

None

4. Fixed Bug

Fixed problems arising during quick test on H6 models